

Inspection Report

01.15.2019

Advantage Inspection Upstate Inc.

Post Office Box 4137 Greenville SC 29608 | 864-298-0409



prepared for
Sample Report

146 City Scape Dr Greenville SC 29681

YOUR inspection report from Advantage Inspection Upstate Inc. opens the door to a world of resource, education, and promotional incentives designed to help protect your largest assets!

Thank you for your Trust in Advantage Inspection Upstate Inc.!

Inspector:

Adrian Smith SC Lic# 2400

Adric mt



Table of Contents

01.15.2019

Advantage Inspection Upstate Inc.

Post Office Box 4137 Greenville SC 29608 | 864-298-0409

Cover	Page 1
Table of Contents	Page 2
Client Letter	Page 3
Conditions / Contract	Page 4 - 5
Report Summary	Page 6 - 7
Photographs	Page 8 - 21
General Information	Page 22
Structural	Page 23
Exterior	Page 24 - 25
Roof & Attic	Page 26
Plumbing	Page 27 - 28
Plumbing - Water Heater	Page 29
Plumbing - Bathroom	Page 30
Electrical	Page 31
Heating	Page 32 - 33
Heating - Fireplace	Page 34
Cooling	Page 35 - 36
HVAC Distribution	Page 37
Interior	Page 38
Insulation & Ventilation	Page 39
Appliances	Page 40
Safety Inspection	Page 41
Supplemental Information	Page 42 - 43

Definition of Evaluation Headings

- S = Satisfactory Component is not necessarily perfect but is functional allowing for normal wear and tear.
- $R = Needs \ repair Component \ does \ not \ function \ properly \ or \ adversely \ affects \ the \ habitability \ of \ the \ dwelling.$
- I = Investigate Further Component warrants further investigation by a specialist or requires subsequent observation(s).
- $NP = Not \ Present Component \ was \ not \ present \ in \ the \ structure$
- NI = Not Inspected Component was not inspected or the inspection was limited for some reason.

Items noted "R" (needing repair) or "I" (needing further investigation) should be repaired and/or evaluated by a qualified repair person prior to purchase or sale.

Version 2.45



Client Letter

01.15.2019

Advantage Inspection Upstate Inc.

Post Office Box 4137 Greenville SC 29608 | 864-298-0405

Dear Sample Report

We want to thank you for selecting Advantage Inspection to conduct the inspection of your new property purchase. We do our very best to provide a comprehensive inspection and report. If after careful review there are any questions that you would like to ask, please do not hesitate to call.

Payment is expected and/or processed at the time of inspection. Inside the client copy of the report, you will find a copy of the invoice for the inspection service.

We appreciate your business and wish you well in your new home!

Sincerely,

Adrian Smith
Advantage Inspection
PO Box 4137
Greenville, SC 29608
864-298-0405
AdrianSmith@advantageinspection.com



Service Contract

01.15.2019

Advantage Inspection Upstate Inc.

Post Office Box 4137 Greenville SC 29608 | 864-298-0405

Client(s): Inspection Address: Inspector:

Inspection Date: Inspection Costs:

REAL ESTATE INSPECTION AGREEMENT PAGE 1 OF 2

SCOPE OF INSPECTION SERVICES (What we WILL inspect): The Company will perform a limited visual inspection (the "Inspection") which will include the following items if present and accessible. These items are generally accepted as "standard" inspection components" required by most nationally recognized inspector associations and regulatory agencies:

General Information: Persons present during the inspection; approximate age of the structure; construction type and style; weather and soil conditions; residence type; number of stories; approximate house orientation; general lot description.

Grounds: Grade/drainage; yard drains; walks and driveways; landscaping; patio/slabs; outside lighting; trees/limbs; fences/gates; outside faucets; retaining walls.

Exterior: Siding; siding cracks; shutters; trim rot; paint and caulking; fascia; soffit /eaves; porch, porch rails; stoop; stoop rails; deck; deck rails; doors; sliding door(s); garage; garage door opener; windows.

Roof: Materials: Roof style; flashing and roof penetrations; skylights; gutters; downspouts; splash blocks; roof framing; ceiling joists; roof decking; water penetration, whole house fan; ventilation; attic access.

Fireplace: General condition; gas logs; damper; chimney condition; flue liner.

Foundation - Basement: Accessible areas; moisture penetration; piers; foundation walls; floor joist and sills; girders; sub floor; floors/slabs; insulation; Crawlspace: Accessible areas; moisture penetration; sump pump; vapor barrier; piers; foundation walls; floor joist and sills; girders; sub floor; ventilation; insulation. Slab condition: Viewable components.

Electrical: Service entrance; service wires- size and types; grounding equipment; main panel; sub panels; over current protection; ground fault protection; 110 volts and 220 volt circuits; receptacles; light fixtures and switches; safety concerns.

HVAC - Heating: Unit manufacturer; model number; serial number; location; air temperature rise; general condition; heating unit description; energy source; system type; total capacity; approximate age. Cooling: Unit manufacturer; model number; serial number; air temperature drop; general condition; cooling unit description; energy, location; total capacity; approximate age.

Plumbing: Water supply; well pump; water shut offs; water pressure; water pipes; water pipe insulation; water heater; waste water disposal; waste and vent pipes; waste pipe support; plumbing fixtures; kitchen sink; laundry connections; dryer exhaust; bath rooms. Interior: Rooms/floors; walls; smoke alarms; ceilings; stairs; doors.

Appliances: - Permanently installed: Dishwasher; disposal; oven; range; refrigerator; trash compactor and microwave.

INSPECTION LIMITATIONS (What we WILL NOT inspect): The Inspection will be a limited visual inspection of the aforesaid items. The Inspection will not be invasive or technically exhaustive, and cannot detect latent conditions or concealed defects such as sewer line back-up or hidden structural damage. The Inspection is intended to reduce risk but will not eliminate risk. Since the Inspection will be based upon visual observations made during a limited time period, the Company will not be responsible for any condition affecting any system or component which is intermittent and not detectable during the Inspection (for example - compromised insulation seals on windows). The Inspector will not light pilot lights, activate the main water, gas or electric systems, energize electrical circuits which are shut off or are otherwise inoperable or operate any system or component which does not respond to normal operating controls.

The Inspection will not include or address the following items: code compliance, durability, environmental concerns INCLUDING MOLD, compliance with any conservation or energy standard, efficiency, fitness for purpose, flood or seismic risks, underground plumbing, future life, future performance, especially that of foundations, insurability, merchantability, obsolescence, quality, safety of any item inspected, septic systems, wells, cisterns, private water supplies water quality or volume, central vacuum systems, solar systems whether active or inactive, security systems, soils systems, lead paint, asbestos, radon, toxic mold, flammable materials, refrigerators, freezers, remote overhead door transmitters/receivers, floor coverings, wall coverings, free standing kitchen appliances, laundry appliances, water conditioners, swimming pools, spas, tennis courts, playground equipment or other recreational or leisure appliances and self-cleaning or continuous-cleaning capabilities of ovens, wood destroying organisms or insects and non-wood infesting insects such as fleas, cockroaches, bees, mites, ticks, flies, etc. unless specifically stated, any opinion in the inspection report pertaining to aforementioned items is to be considered partial and incomplete.

WRITTEN OR ELECTRONIC INSPECTION REPORT: The Company will render a written and or electronic inspection report outlining the condition of items inspected as they existed at the time of the Inspection (the "Report"). The Report will contain the opinions of the Inspector which opinions may change should conditions change which affect the items inspected. Although code compliance and engineering evaluation are specifically excluded from the Inspection, some codes may be used as a reference or basis for the opinion of the Inspector. The inspection services to be provided are further defined and limited by the Report and any attachments thereto. The Company will provide the Report to the Client, or Client's authorized representative (person(s) ordering inspection, submitting payment, or otherwise designated to represent the Client). Distribution of copies of the Report to other parties will be at Client's direction, or as otherwise specified by law. The Report will not be released until payment is received by the Company.

			-	-	 -	-	-	-	•
In	ti	a	ls	s					

CLIENT RESPONSIBILITY: The Client is responsible for arranging access to the structure to be inspected and is responsible for insuring that all utilities are operational prior to the scheduled Inspection. The attendance of Client during the Inspection is encouraged however Client acknowledges that attendance at the inspection is at the Client's or any other attending party's own risk.

GENERAL STATEMENTS AND AGREEMENTS THAT APPLY TO HOME INSPECTIONS: Before completion of any contractual agreements on the Property, Client should obtain second opinions or cost estimates by appropriate specialists on items where performance may be reported as questionable, in need of repair or servicing or unsafe. It is specifically understood and agreed that the Inspection Company and the Clients are bound only by the terms and conditions of this Agreement and have not relied on any other representations, oral or otherwise.

DISCLAIMER OF WARRANTIES AND GUARANTEES - The Inspection Company or inspector(s) make no guarantee or warranty as to any of the following:

- 1. that all repair needs and hazards have been discovered or disclosed in accessible or inaccessible areas.
- 2. That inspection company or the inspector will pay for the repair of undiscovered problems or conditions.
- 3. That any of the items inspected are designed or constructed in a good or workmanlike manner.
- 4. That any of the items inspected will continue to perform in the future as they are performing at the time of inspection.
- 5. That the building will not experience or contain wood destroying insect activity or damage.
- 6. No guaranty or warranty of merchantability or fitness of use of the condition of the property.

LIMITS OF LIABILITY: Home inspections are not insurance and do not provide protection against unexpected conditions or repair /replacement needs and costs. The Client acknowledges that there are risks involved in purchasing property, and while the ordering of a home inspection may reduce the risks, risk cannot be eliminated. Client acknowledges that the Company is not an insurer and does not insure against defects in the Property. The maximum liability of the Company or its employees for errors and omissions in the inspection process shall be

Limited to the amount of the fee paid for the applicable inspection. Client agrees to pay all legal expenses and reasonable compensation for loss of time that may be incurred by any inspector, owner or employee of the Company as a result of any legal action brought by the Client where the Client does not prevail. Client understands that comprehensive inspections may be available from other companies.

DISPUTE RESOLUTION: Should a concern or dispute arise over the condition of an inspected item after the date of the inspection, Client agrees to notify the Company in writing within fourteen (14) days of the discovery of the condition and provide the Company with the opportunity to re-inspect the disputed item and document any concerns prior to the commencement of repair or replacement work. Notwithstanding the above, immediate repairs should be made regardless of whether or not the Company has been given the opportunity to re-inspect a condition should circumstances warrant immediate repair. However, Client's failure to give the Company notice and the opportunity to re-inspect an item where immediate repairs are not required to protect life or property shall preclude Client from pursuing a claim against the Company for that item. In no event shall any action be brought against the inspection company for a breach of this Agreement at any time beyond one (1) year after the date of this Agreement.

MISCELLANEOUS - Entire Agreement: This Agreement, and the Inspection Report issued by the Company, constitutes the sole Agreement between Client and the Company. Third Party Indemnification: All services are performed and the Report is prepared for the sole and exclusive use and benefit of the Client. The Report is not intended for the use or benefit of anyone other than the Client and no third party shall have any right arising from the Inspection or the Report. Reports are non-transferable and may not be relied upon by other parties without the written consent of both the Client and the Company, unless otherwise specified by law. In consideration of the Company furnishing the Report, Client will indemnify and hold the Company harmless from any claims, demands or costs as a result of any third party demand or claim arising out of the Inspection or the Report. Applicable law: This report shall be construed under the laws of the state in which the inspection was performed. Seller's Disclosure: The Report will be supplemental to any real estate transfer or seller's disclosure statement and shall not be used as a substitute for such disclosure statements. Wherever there is a reference herein to the Client, the singular includes the plural and the masculine includes the feminine and the neuter. By signing below, I acknowledge that I have read this Agreement, that I understand the terms and conditions hereof and I agree to be bound by these terms and conditions

COMPANY RELATIONSHIPS with third party providers. (Your company name). has affiliations with third party providers, Lowes, Nationwide Insurance, ADT, etc. These providers may offer special, value added services / discounts for our clients. By signing this contract below, you authorize these vendors to contact you about these services. These providers are approved by Advantage Inspection Greenville.

The Client agrees to allow the inspection company to upload the client's inspection report to inspectornetwork.com for data storage / backup for confidential online distribution at the client's direction.

CLIENT(S):	DATE:	NOTE: THIS LAST PAGE OF THE INSPECTION AGREEMENT
MUST BE SIGNED AND RETURNED TO OUR OFFI	CE WITH THE INSPECTION	NAUTHORIZATION COMPLETED PRIOR TO THE DAY OF
INSPECTION.		



Report Summary

Advantage Inspection Upstate Inc.

Post Office Box 4137 Greenville SC 29608

Prepared For:

Inspection Address:

Real Estate Agent:

THIS SUMMARY IS NOT THE ENTIRE REPORT. THE COMPLETE REPORT MAY INCLUDE ADDITIONAL INFORMATION OF CONCERN TO THE CLIENT. IT IS STRONGLY RECOMMENDED THAT THE CLIENT READ THE COMPLETE REPORT. THIS SUMMARY INCLUDES ONLY THOSE ITEMS THAT DO NOT FUNCTION PROPERLY OR ADVERSELY AFFECT THE HABITABILITY OF THE DWELLING; OR APPEARS T WARRANT FURTHER INVESTIGATION BY A SPECIALIST, OR REQUIRES SUBSEQUENT OBSERVATION(S).

THE FOLLOWING ITEMS SHOULD BE CHECKED FOR EXTENT OF DAMAGE AND/OR REPAIRED BY QUALIFIED REPAIR PERSON

Needs Repair

Exterior

- 1. Gaps noted between brick and vinyl siding along the front porch and at the front right corner of the home. Recommend having a qualified person properly seal the gaps to eliminate water penetration.
- 1a. Recommend sealing gaps in siding where pipes enter the right side of the basement.
- 1b. Bottom row of siding is loose along the rear deck. Gaps noted in corners of the siding. Recommend having a licensed contractor properly install the bottom row of siding.
- 2. Window screens are stored in the basement. Check screens for proper sizing and condition.
- 2a. Window shutters are loose along front of the home. Loose window shutters need to be secured in place.
- 2b. Paint is peeling from exterior windows and window frames around the home. Recommend having a qualified person paint the windows and frames with proper preparation.
- 2c. Wood rot noted along the exterior window frames at the front dining room windows. Recommend having a qualified person repair the damaged
- 3. Recommend pressure washing and applying a wood preservative to the deck and deck railings.
- 4. Voids noted under the driveway along both ends of the garage. The driveway has settled. Recommend having a licensed contractor evaluate the driveway and make necessary repairs to the driveway.
- 5. Wood rot noted to casement at the rear basement entry door. Recommend having a qualified person repair the damaged wood.
- 6. The walkway has settled and is damaged beside the front porch steps. Recommend having a licensed contractor evaluate the sidewalk and make
- 7. Recommend trimming bushes and vines away from the house.
- 8. Raised nails noted along the left rear stoop and stoop steps. Recommend having a qualified person secure the loose nails in place to prevent injury.
- 8a. A partial brace has been installed under the stairs at the left side stoop. Recommend having a qualified person finish the brace to add proper support to the stairs.
- 9. Recommend sealing gap where pipe exits the soffit along rear of the home over the deck.
- 10. Settling cracks noted along the garage ceiling. Suggest patching the cracks.
- 10a. Lens is loose at the garage door opener. Recommend securing the cover lens in place.
- 10b. Water stains noted along the garage ceiling and wall. Newer roof appears to have eliminated leaks. Ceiling and wall are dry at time of the inspection. Suggest painting the ceiling and wall with proper preparation.
- 11. Loose mortar joints noted along the front porch and porch steps. Recommend having a qualified person properly seal the loose mortar joints to prevent settling from water penetration.

- 12. Downspout is loose along rear of the home at the deck. Recommend having a qualified person secure the loose downspout in place.
- 13. Unable to determine where downspout drain pipe discharges along left side of the front porch. Check with the current owner for location of the downspout drain pipe to ensure water is properly diverted away from the sidewalk.

14. The rear exterior faucet drips continuously. Recommend having a qualified person repair or replace the rear faucet to eliminate the drip.

Plumbing - Bathroom

- 15. Toilet is loose from the floor in the first floor hall bathroom. Toilet needs to be secured to floor flange to prevent leaks.
- 16. Recommend sealing gap between the shower and floor in the master bathroom to prevent water penetration.
- 16. Recommend sealing gap between the snower and moor in the master bathroom to prove the second floor front bedroom bathroom. The handle must be turned back slightly Page 6 of 43

to turn the water off. Recommend having a licensed contractor repair or replace the shower faucet handle to allow the faucet handle to properly tun off the water.

18. Vinyl floor is damaged beside the basement bathroom bathtub. Recommend having a qualified person replace the damaged vinyl flooring.

Electrical

- 19. Ground fault receptacle does not trip in the second floor front bedroom bathroom. Recommend having a licensed contractor replace the GFI receptacle.
- 20. Kitchen can light is out. Replace bulb to ensure the fixture operates.

Heating

21. Standing water noted in the drain pan of the basement furnace. The furnace sump pump is not operating. Recommend having a licensed contractor replace the sump pump.

Interior

- 22. Carpets are wrinkled and need stretching along the second floor. Carpets can be a tripping hazard.
- 22a. Slope noted to the first floor hallway beside the hall bathroom. Finished ceiling in the basement under this area prevents viewing the floor framing. Flooring feels secure. Water stains noted to the wood flooring in the front office. Recommend repairing the flooring.
- 23. The first floor hall bathroom door sticks when closing. Recommend adjusting or trimming the door to allow proper closure.
- 23a. The master bedroom closet doors drag against the bathroom floor tiles. Closet doors need to be adjusted to prevent damage to the door or flooring.
- 24. Water stain noted to the front coat closet ceiling. No evidence of active leaks observed over this area. Ceiling is dry at time of the inspection. Suggest painting the ceiling with proper preparation.
- 25. Windows are stuck and hard to open through the home. Recommend freeing at least one window in every room to allow emergency egress.

Appliances

26. A visible high loop is not present at the dishwasher drain line. Recommend having a qualified person install a high loop or an air gap at the dishwasher drain line to prevent water from backing up into the dishwasher.

Gaps noted between brick and vinyl siding along the front porch and at the front right corner of the home. Recommend having a qualified person properly seal the gaps to eliminate water penetration.



Loose mortar joints noted along the front porch and porch steps. Recommend having a qualified person properly seal the loose mortar joints to prevent settling from water penetration.



The walkway has settled and is damaged beside the front porch steps. Recommend having a licensed contractor evaluate the sidewalk and make necessary repairs.



Gaps noted between brick and vinyl siding along the front porch and at the front right corner of the home. Recommend having a qualified person properly seal the gaps to eliminate water penetration.



Recommend trimming bushes and vines away from the house.



AC units are located along right side of the home.



Recommend sealing gaps in siding where pipes enter the right side of the basement.



Paint is peeling from exterior windows and window frames around the home. Recommend having a qualified person paint the windows and frames with proper preparation.



Recommend pressure washing and applying a wood preservative to the deck and deck railings.



Bottom row of siding is loose along the rear deck. Gaps noted in corners of the siding. Recommend having a licensed contractor properly install the bottom row of siding



Raised nails noted along the left rear stoop and stoop steps. Recommend having a qualified person secure the loose nails in place to prevent injury.



A partial brace has been installed under the stairs at the left side stoop. Recommend having a qualified person finish the brace to add proper support to the stairs.



Voids noted under the driveway along both ends of the garage. The driveway has settled. Recommend having a licensed contractor evaluate the driveway and make necessary repairs to the driveway.



Voids noted under the driveway along both ends of the garage. The driveway has settled. Recommend having a licensed contractor evaluate the driveway and make necessary repairs to the driveway.



Unable to determine where downspout drain pipe discharges along left side of the front porch. Check with the current owner for location of the downspout drain pipe to ensure water is properly diverted away from the sidewalk.



Wood rot noted along the exterior window frames at the front dining room windows. Recommend having a qualified person repair the damaged wood.




Wood rot noted along the exterior window frames at the front dining room windows. Recommend having a qualified person repair the damaged wood.




Window shutters are loose along front of the home. Loose window shutters need to be secured in place.



Settling cracks noted along the garage ceiling. Suggest patching the cracks.



Lens is loose at the garage door opener. Recommend securing the cover lens in place.



Water stains noted along the garage ceiling and wall. Newer roof appears to have eliminated leaks. Ceiling and wall are dry at time of the inspection. Suggest painting the ceiling and wall with proper preparation.




A visible high loop is not present at the dishwasher drain line. Recommend having a qualified person install a high loop or an air gap at the dishwasher drain line to prevent water from backing up into the dishwasher.



Slope noted to the first floor hallway beside the hall bathroom. Finished ceiling in the basement under this area prevents viewing the floor framing. Flooring feels secure.



Water stain noted to the front coat closet ceiling. No evidence of active leaks observed over this area. Ceiling is dry at time of the inspection. Suggest painting the ceiling with proper preparation.



Water stains noted to the wood flooring in the front office. Recommend repairing the flooring.



Recommend sealing gap between the shower and floor in the master bathroom to prevent water penetration.



Bathtub faucet handle runs when turned to the off position in the second floor front bedroom bathroom. The handle must be turned back slightly to turn the water off. Recommend having a licensed contractor repair or replace the shower faucet handle to allow the faucet handle to properly tun off the water.



Vinyl floor is damaged beside the basement bathroom bathtub. Recommend having a qualified person replace the damaged vinyl flooring.



Wood rot noted to casement at the rear basement entry door. Recommend having a qualified person repair the damaged wood.



Water pressure regulator(top) and main water shut off valves(bottom) are located in the basement along front of the home.



Sump pump is located in the basement.




Home has a passive radon vent pipe installed.




The gas water heater is located in the basement.



Gas furnace in the basement serves the first floor and basement.



Standing water noted in the drain pan of the basement furnace. The furnace sump pump is not operating. Recommend having a licensed contractor replace the sump pump.



Gas furnace in the attic serves the second floor.



View of the second floor attic framing.



View of the second floor attic.



View of the attic over the master bedroom.



Report Number T2U144R66190

INSPECTION PICTURE ADDENDUM

View of the attic over the master bedroom.



***** GENERAL COMMENTS ON THE INSPECTION *****

PLEASE REVIEW ENTIRE REPORT CAREFULLY. FOR QUICK REFERENCE OF DEFECTIVE ITEMS AND INSPECTOR NOTES, REFER TO THE SUMMARY PAGE AT THE BEGINNING OF THE REPORT.

INSPECTION TIME

9:00 AM

PEOPLE PRESENT AT THE INSPECTION

Buyer & Agent

APPROXIMATE AGE

Per Realtor, house was built about 1997

HOME STYLE

Traditional

CONSTRUCTION TYPE

Wood Frame

WEATHER AND SOIL CONDITIONS

Clear at the time of inspection with recent rain.

TEMPERATURE

46 Degrees Fahrenheit

STRUCTURE OCCUPIED

Yes

RESIDENCE TYPE

Single family detached

NUMBER OF STORIES

Two with basement

APPROXIMATE HOUSE ORIENTATION

Northeast

LOT DESCRIPTION

Typical residential lot.

S = Item is satisfactory	R = Item needs repair	I = Item needs investigated	\mathbf{NP} = Item not present	NI = Item not inspected
STRUCTURAL	Report Number T2U144R66190		= Tips, Tools, and	Savings S R I NP NI
		FOUNDATION DETAILS		
FOUNDATION- Bases	ment			
INSPECTION METHO	DD & ACCESSIBLE AREAS			
Attic areas were inspecte	d by walking through them.			
FLOOR/SLAB- Conc	rete, Gravel			
SUBFLOOR- OSB				
PIER/COLUMNS/FOU	ND. WALL- Masonry			
FLOOR JOIST & SILI	S- Conventional framing			
	20			[-]
GIRDER- Double, wo	od			
MOISTURE Woo	od Moisture content 10-12 %	Acceptable levels are below 19%		
SUMP PUMP				
CRAWL SPACE VAPO	OR BARRIER- Plastic			
		ROOF DETAILS		
ROOF FRAMING-	Conventional rafter & bracing	NOOT DETINED		
CEILING JOISTS-	Conventional joist & bearing			
ROOF DECKING- O	SB			
		WALL DETAILS		
EXTERIOR/INTERIO	R WALLS			
	ADDITI	ONAL STRUCTURAL ITEM (IF N	NEEDED)	
		(H 1	,	

S = Item is satisfactory	•	I = Item needs investigated	\mathbf{NP} = Item not present	NI= Item not inspected
EXTERIOR	Report Number T2U144R66190		= Tips, Tools, and Sav	vings S R I NP NI
WALL CLADDING-	Vinyl, Brick			
properly seal the gaps to Recommend sealing ga Bottom row of siding is the bottom row of sidin	e	de of the basement. corners of the siding. Recommend h	naving a licensed contractor prop	-
	ps in siding where pipes enter the right sid	de of the home to prevent water pene	etration.	
FLASHING				
TRIM				
FRONT DOOR-	Double Fiberglass Glass	Metal Single	Wood	
REAR DOORS-	Double Fiberglass Glass	✓ Metal ✓ Single	Wood	
Wood rot noted to case	ment at the rear basement entry door. Rec		repair the damaged wood.	
SIDE DOORS-	Double Fiberglass Glass	✓ Metal ✓ Single	Wood	
SLIDING GLASS DO	OR- Insulated Screened	Tempered		
WINDOWS- (exterior side)			Slider Vinyl Storm Wood	
Window shutters are lo- Paint is peeling from ex- frames with proper prep	ored in the basement. Check screens for properties along front of the home. Loose windowsterior windows and window frames around paration. The exterior window frames at the front directions are the front directions.	w shutters need to be secured in place and the home. Recommend having a commend having havi	qualified person paint the window	
GARAGE- Two car	attached DOOR OPI	ENER- Genie (auto reverse)		
Lens is loose at the gara Water stains noted alon	ong the garage ceiling. Suggest patching tage door opener. Recommend securing the garage ceiling and wall. Newer roof nting the ceiling and wall with proper pre-	e cover lens in place. appears to have eliminated leaks. C	eiling and wall are dry at time of	f the
DECK- Wood				
Recommend pressure w	vashing and applying a wood preservative	to the deck and deck railings.		
DECK RAILS- Woo	od			
EXTERIOR BALCON	NY-			
EXTERIOR BALCON	NV RAILS.			
EXTERIOR BALCOI	VI KAILS-			
STOOP- Wood	4.10	11 ' " "	4.1 9.1	
injury.	g the left rear stoop and stoop steps. Reco			
STOOP RAILS- Wo	ood			

S = Item is satisfactor		I = Item needs investigated	$\mathbf{NP} = \mathbf{Item} \ \mathbf{not} \ \mathbf{present}$	NI= Item not inspected
EXTERIOR	Report Number T2U144R66190		= Tips, Tools, and	d Savings S R I NP NI
PORCH- Masonry	,			
Loose mortar joints no prevent settling from v	ted along the front porch and porch step	s. Recommend having a qualified p	person properly seal the loose m	nortar joints to
PORCH RAILS-	vator penetration.			
SOFFIT/EAVES- V				
	ap where pipe exits the soffit along rear	of the home over the deck.		
FASCIA- Alu	m. clad			
				<u> </u>
DRIVEWAY- Co	ncrete			
	driveway along both ends of the garage	. The driveway has settled. Recomm	nend having a licensed contract	<u> </u>
	cessary repairs to the driveway.			
PATIOS/SLABS-	oncrete			
WALKS- Concrete				
The walkway has settle necessary repairs.	ed and is damaged beside the front porc	h steps. Recommend having a licens	sed contractor evaluate the side	walk and make
RETAINING WALL	 S-			
RETAILUNG WILLE	5-			<u> </u>
VEGETATION- Gra	ace / Trees			
	bushes and vines away from the house.			
TREES/LIMBS				
GRADE/DRAINAGE				
	ADDITI	ONAL EXTERIOR ITEMS (IF N	(EEDED)	

S = Item is satisfactory $R = Item needs repair$ $I = Item needs investigated$	\mathbf{NP} = Item not present	NI = Item not inspected
ROOF Report Number T2U144R66190	III = Tips, Tools, and Sa	vings S R I NP NI
ROOF COVERINGS- Fiberglass / Asphalt Composition ROOF STYLE- Gable & Hip		
GUTTERS- Aluminum		
DOWNSPOUTS- Aluminum		
Downspout is loose along rear of the home at the deck. Recommend having a qualified person secure	the loose downspout in place.	
SPLASH BLOCKS DISCHARGE- Plastic pipe		
Unable to determine where downspout drain pipe discharges along left side of the front porch. Check downspout drain pipe to ensure water is properly diverted away from the sidewalk.	with the current owner for loca	ition of the
FLASHING & ROOF PENETRATIONS		
SKYLIGHTS		
WATER PENETRATION		
ADDITIONAL ROOF ITEMS (IF NEEDI	ED)	
	,	✓
ROOF INSPECTED FROM:		
The roof was inspected from attic & grade.		
ROOF AREAS NOT INSPECTED		iii
No inaccessible areas on the roof.		
Note: Items noted "R" (needing repair) or "I" (needing further investigation) should be repaired purchase or sale. Apparent serviceability of roofing system is reported but is not a warranty or a home inspector is NOT required to walk on the roofing or inspect attached accessories including	guarantee of the remaining life e	xpectancy. The

Page 26 of 43

S = Item is satisfactory	R = Item needs repair	I = Item needs investigate	\mathbf{NP} = Item not present	NI = Item not inspected
	Report Number T2U144R66190		III = Tips, Tools, and Sa	avings S R I NP NI
		WATER SUPPLY DETA	ILS	
WATER SUPPLY TYPE	Public Sewer I	Public Water Septic	Well	
WATER SUPPLY-	Copper Galvanized	Not visible Pex	Polybutylene PVC	
WELL PUMP- Manufact	urer	Est. Age.		
WATER SHUT OFF LO Water pressure regulator(to	CATION- Foundation pop) and main water shut off valves	Meter Water hea s(bottom) are located in the base		
WATER PRESSURE	Approximate P.S.I.G.	65		
		WATER DISTRIBUTION D	ETAILS	
WATER PIPES-	Copper CPVC	Galvanized Pex	Polybutylene	
FUNCTIONAL FLOW Functional water flow was	observed at all fixtures where test	ting was possible and practical.	Washing machine water flow was not te	isted.
WATER PIPE SUPPOR				
WATER PIPE INSULAT	TION			
		WASTE & VENT PIPE DE	TAILS	
WASTE & VENT PIPES	Cast Iron Copper	Galvanized V PVC		V
The drainage system was t		I fixtures and drains except the	washing machine drain. Functional drair	age appeared
normal.		Third of the control	The state of the s	
WASTE & VENT PIPE S	SUPPORT			
		EQUIPMENT & FUEL STO	RAGE	
WASTE PUMP (SOMET	TIMES CALLED A LIFT STAT			
INTERIOR FUEL STOR	RAGE / FUEL SUPPLY & VEN	T PIPING		
		DI HADDING ELVEHDE		
OUTSIDE FAUCETS		PLUMBING FIXTURE	Ci.	
	ips continuously. Recommend hav	ring a qualified person repair or	replace the rear faucet to eliminate the c	
KITCHEN SINK				

S = Item is satisfactory	R = Item needs repair	I = Item needs investigat	ted NP = Item not present	NI = Item not inspected
PLUMBING	Report Number T2U144R66190		= Tips, Tools, a	nd Savings C D I ND NI
	120144100190		= 1 lps, 100ls, a	nd Savings S R I NP NI
LAUNDRY CONNECT	TIONS- Elect. Dryer Gas	Dryer Mop Sink	Washer	
Water and drain connection	ons for washer and outlet for dryer of	oserved only. Not tested.		
	-			
	ADDITI	ONAL PLUMBING ITEMS	S (IF NEEDED)	
RADON VENT PIPE				✓
Home has a passive rador	n vent pipe installed.			

S = Item is satisfactory	\mathbf{R} = Item needs repair	$\mathbf{I} = \text{Item needs}$	s investigated	\mathbf{NP} = Item not present	NI = Ite	em n	ot ins	pecte	:d
PLUMBING	Report Number T2U144R66190	WATER HEAT	ΓER	= Tips, Tools, and S	Savings	s 1	R I	NP	NI
WATER HEATER	Water Heater Location Basement		50	Gallon					
# 1	Manufacturer A. O. Smith		Serial Number	1403A022024	L	\bot			
	Estimated Age 5		Model Number	GPV50200	~	1	_	Ш	Ш
	Electric Gas I	Propane Tan	Water Temperature	115					

Note: Items noted "R" (needing repair) or "I" (needing further investigation) should be repaired and/or evaluated by a qualified repair person prior to purchase or sale. If well water is used for drinking purposes, we recommend it be tested by a lab or the health dept. Underground septic systems, sewer lines, and water treatment equipment are not inspected. If present, we recommend a septic system inspection and/or contractor evaluation before closing. The home inspector is not required to: state the effectiveness of anti-siphon devices; determine whether water supply and waste disposal systems are public or private; operate automatic safety controls; operate any valve except water closet flush valves, fixture faucets, and hose faucets. The home inspector is not required to inspect: water conditioning systems; fire and lawn sprinkler systems; on-site water supply quantity and quality; on-site waste disposal systems; foundation irrigation systems; bathroom spas, except as to functional flow and functional drainage; swimming pools; solar water heating equipment; or inspect the system for proper sizing, design, or use of proper materials.

S = Item is satisfactory	\mathbf{R} = Item needs repair	I = Item needs investigated	\mathbf{NP} = Item not present	NI = Item not inspect	ted
	Report Number T2U144R66190	BATHROOM	= Tips, Tools, and Sa	avings SRINP	NI
BATH FIXTURES #1-	First floor hall bathroom				
Toilet is loose from the flo	oor in the first floor hall bathroom.	Toilet needs to be secured to floor flan	nge to prevent leaks.		
BATH FIXTURES #2-	Master bathroom				
Recommend sealing gap b	between the shower and floor in the	e master bathroom to prevent water per	netration.		
BATH FIXTURES #3-	Second floor hall bathroom			□ ✓	
BATH FIXTURES #4-	Second floor front bedroom bat	throom			
		n the second floor front bedroom bathro			
to turn the water off. Reco	ommend having a licensed contract	tor repair or replace the shower faucet l	handle to allow the faucet handle	to properly	
tuli off the water.					
BATH FIXTURES #5-				□ ✓	
Vinyl floor is damaged be	side the basement bathroom bathtr	ub. Recommend having a qualified per	son replace the damaged vinyl flo	oring.	

Note: Items noted "R" (needing repair) or "I" (needing further investigation) should be repaired and/or evaluated by a qualified repair person prior to purchase or sale. If well water is used for drinking purposes, we recommend it be tested by a lab or the health dept. Underground septic systems, sewer lines, and water treatment equipment are not inspected. If present, we recommend a septic system inspection and/or contractor evaluation before closing. The home inspector is not required to: state the effectiveness of anti-siphon devices; determine whether water supply and waste disposal systems are public or private; operate automatic safety controls; operate any valve except water closet flush valves, fixture faucets, and hose faucets. The home inspector is not required to inspect: water conditioning systems; fire and lawn sprinkler systems; on-site water supply quantity and quality; on-site waste disposal systems; foundation irrigation systems; bathroom spas, except as to functional flow and functional drainage; swimming pools; solar water heating equipment; or inspect the system for proper sizing, design, or use of proper materials.

Report Number	NP = Item not present	NI = Item not inspected
ELECTRICAL T2U144R66190	III = Tips, Tools, and	d Savings S R I NP NI
SERVICE ENTRANCE- Underground		
SERVICE WIRES SIZE & TYPE- 4/0 Aluminum = 200 Amps & 240 Volts		
GROUNDING EQUIPMENT- Not Present To Ground Stake To Water Pipe		
MAIN PANEL- Located at- Laundry Room		
SUB PANELS- Located at-		
OVER CURRENT/FAULT PROTECTION- ARC Breaker Circuit Breakers Fu	uses GFCI	Brea 🔑 🗸
CDOUND FAILUT		
GROUND FAULT PROTECTION- Baths Exterior Kitchen		
Currently present at: Carport Garage None		
Ground fault receptacle does not trip in the second floor front bedroom bathroom. Recomm GFI receptacle.	mend having a licensed	l contractor replace the
110 VOLT CIRCUITS - Material Aluminum Copper Could not	Inspect	
220 VOLT CIRCUITS - Material- Aluminum Copper Could not	Inspect	
RECEPTACLES (representative #)- Type- 2 Prong 3 Prong		
INTERIOR LIGHT FIXTURES, CEILING FANS & SWITCHES		
Kitchen can light is out. Replace bulb to ensure the fixture operates.		
EXTERIOR LIGHT FIXTURES, CEILING FANS & SWITCHES		
SMOKE DETECTORS		
DOORBELL		
ADDITIONAL ELECTRICAL ITEM (IF NEED	DED)	

S = Item is satisfactory	\mathbf{R} = Item need	ls repair	I = Item needs i	nvestigated	\mathbf{NP} = Item not present	NI = Item not inspected
HEATING	Report Number T2U144R66190				■ Tips, Tools, a	and Savings S R I NP NI
HEATING UNIT ME	FG # 1	HEATING UNI	Γ DESCRIPTION	N	SYSTEM	ТҮРЕ
Lennox		Baseboard	Heat Pump	Mini-Split	✓ Central	Package System
MODEL NUMBER		Forced Air	Hot Water	Radiant He	Room unit	Split System
G51MP-36C-090-03		Torced Air	IIot water	Kadiani He	Koom unit	Split System
SERIAL NUMBER					UNITE LOCATION	,
5905A03869		TOTAL CAPAC	CITY(in BTU's)		UNIT LOCATION	
ENERGY SOURCE		90,000 BTU's	,		Attic	Inside
Electric Oil					✓ Basement	Outside
Natural Gas Pro	pane	APPROXIMAT	E AGE (in years)		Crawlspace	
Area Served:		2005			Garage	
First Floor and Basement						
HEATING EQUIPM Standing water noted in the contractor replace the sun OPERATION - AIR TE The temperature output w	ne drain pan of the banp pump. MP. RISE R	Seturn - 80	Supply -	103		
OPERATING & SAFET	TY CONTROLS					
FLUE						
		ADDITIC	NAL HEATING	ITEM (IF NEED)	ED)	
		, in the second		TIENI (II TVEED)		
HEATING UNIT ME	FG # 2	HEATING UNI	T DESCRIPTION	N	SYSTEM	TYPE
Heil		Baseboard	Heat Pump	Mini-Split	✓ Central	Package System
MODEL NUMBER G9MXE0601412A		Forced Air	Hot Water	Radiant He	Room unit	Split System
SERIAL NUMBER						
A124459746		TOTAL CAPAC	CITY(in RTII's)		UNIT LOCATION	\
ENERGY SOURCE		60,000 BTU's	211 1 (iii B10 s)			
Electric Oil		00,000 D10 3			✓ Attic	Inside
Electric Oil		00,000 B1C s			Attic Basement	Inside Outside
	pane	APPROXIMAT	E AGF (in years)			<u></u>
	pane	,	E AGF(in years)		Basement	<u></u>
Natural Gas Pro	pane	APPROXIMAT	E AGE(in years)		Basement Crawlspace	<u></u>
Natural Gas Pro Area Served: Second Floor	pane	APPROXIMAT	E AGE(in years)		Basement Crawlspace	Outside
Natural Gas Pro Area Served: Second Floor HEATING EQUIPM OPERATION - AIR TE	ENT MP. RISE R	APPROXIMAT 2017	Supply -		Basement Crawlspace Garage	Outside
Natural Gas Pro Area Served: Second Floor HEATING EQUIPM	ENT MP. RISE R	APPROXIMAT 2017	Supply -		Basement Crawlspace Garage	Outside
Natural Gas Pro Area Served: Second Floor HEATING EQUIPM OPERATION - AIR TE	ENT MP. RISE R ith respect to return to	APPROXIMAT 2017	Supply -		Basement Crawlspace Garage	Outside
Natural Gas Pro Area Served: Second Floor HEATING EQUIPM OPERATION - AIR TE The temperature output w	ENT MP. RISE R ith respect to return to	APPROXIMAT 2017	Supply -		Basement Crawlspace Garage	Outside

S = Item is satisfactory	R = Item needs repair Report Number	I = Item needs investigated NP	= Item not present	NI = Item not inspected
HEATING	T2U144R66190		III = Tips, Tools,	and Savings SRINPNI
	AD	DITIONAL HEATING ITEM (IF NEEDED)	1	

Note: Items noted "R" (needing repair) or "I" (needing further investigation) should be repaired and/or evaluated by a qualified repair person prior to purchase or sale. For gas or oil furnaces, the only cover that was removed was the access cover on the burner assembly. The heat exchanger cannot be examined without extensive disassembly of the cabinet. Since this is not possible during a standard, visual home inspection, you may want to obtain a warranty contract on heating units and / or have heat exchanger technically evaluated by an HVAC technician prior to sale. Cracks in flue liners are often concealed by the normal build up of creosote. Our visual inspection may not detect all possible problems with chinmeys. The home inspector is not required to: operate heating systems when weather conditions or other circumstances may cause equipment damage; operate automatic safety controls; ignite or extinguish solid fuel fires; or ignite a pilot light. The home inspector is not required to inspect: the interior of flues; fireplace insert flue connections; heat exchanger; humidifiers; electronic air filters; the uniformity or adequacy of heat supply (air flow) to the various rooms; or solar space heating equipment.

S = Item is satisfactory		needs repair	I = Item needs investigated	NP = Item not present	NI = Item not inspected
HEATING	Report Number T2U144R66190		FIREPLACE	i = Tips, Tools, ar	nd Savings S R I NP NI
FIREPLACE # 1-	Description:	Metal	Location:	Living Room	
GAS LOGS					
Gas fireplace logs opera	ted normally during	ng inspection.			
DAMPER					
CHIMNEY/FLUE CO	NDITION				
CHIMNE 1/FLUE CO	NUTTION				→ []
		A D.D	MITIONAL EIDEDLAGE ITEM (IE	NEEDED)	
		ADL	DITIONAL FIREPLACE ITEM (IF	NEEDED)	

Note: Items noted "R" (needing repair) or "I" (needing further investigation) should be repaired and/or evaluated by a qualified repair person prior to purchase or sale. For gas or oil furnaces, the only cover that was removed was the access cover on the burner assembly. The heat exchanger cannot be examined without extensive disassembly of the cabinet. Since this is not possible during a standard, visual home inspection, you may want to obtain a warranty contract on heating units and / or have heat exchanger technically evaluated by an HVAC technician prior to sale. Cracks in flue liners are often concealed by the normal build up of creosote. Our visual inspection may not detect all possible problems with chinmeys. The home inspector is not required to: operate heating systems when weather conditions or other circumstances may cause equipment damage; operate automatic safety controls; ignite or extinguish solid fuel fires; or ignite a pilot light. The home inspector is not required to inspect: the interior of flues; fireplace insert flue connections; heat exchanger; humidifiers; electronic air filters; the uniformity or adequacy of heat supply (air flow) to the various rooms; or solar space heating equipment.

S = Item is satisfactory	= Item needs repair	I = Item needs investigated	\mathbf{NP} = Item not present	NI = Item not inspected
AIR CONDITIONING	Report Number T2U144R66190		III = Tips, Tools, and	Savings S R I NP NI
A/C MFG UNIT # 1	SYSTEM	ТҮРЕ	LOCATION	
Lennox	✓ Central	Dual zone	Inside	
MODEL NUMBER	Room units	Package system	Outside	
10ACC-036-230-04		Split system		
SERIAL NUMBER		Spin system		
5805D42324			ENERGY	
TOTAL CAPACITY(in Tons)	APPROXIMATI	E AGE(in years)	✓ Electric	
3 tons	2005		Gas	
AREA SERVED:			Gus	
First Floor and Basement				
A/C EQUIPMENT				
OPERATION - AIR TEMP. DRO	OP Return -	Supply -		
The outside A/C condensing unit w	as not tested due to manufact	urer's recommendations not to op	erate when the outdoor tempera	ture is less
than 65 degrees. The unit did switch	to cooling when thermostat	was activated.		
A/C OPERATING CONTROLS				
	ADDI	TIONAL A/C ITEM (IF NEED	(ED)	
A/C MFG UNIT # 2	SYSTEM	ТҮРЕ	LOCATION	
Heil	Central	Dual zone	Inside	
MODEL NUMBER				
NXA424CKCK01	Room units	Package system	✓ Outside	
SERIAL NUMBER		Split system		
E173227730			ENERGY	
TOTAL CAPACITY(in Tons)	APPROXIMATI	F. ACF(in years)	Electric	
2 tons	2017	E AGEIN yeurs)		
AREA SERVED:			Gas	
Second Floor				
A/C EQUIPMENT				
OPERATION - AIR TEMP. DRO		Supply -	41 41414	
The outside A/C condensing unit we than 65 degrees. The unit did switch			erate when the outdoor tempera	ture is iess
A/C OPERATING CONTROLS				
	ADDI	ΓΙΟΝΑL A/C ITEM (IF NEED	DED)	

S = Item is satisfactory

AIR CONDITIONING

R = Item needs repair Report Number T2U144R66190

I = Item needs investigated

NP = Item not present

NI = Item not inspected

= Tips, Tools, and Savings SRINNNI

Note: Items noted "R" (needing repair) or "I" (needing further investigation) should be repaired and/or evaluated by a qualified repair person prior to purchase or sale. This report does not reflect a technically exhaustive evaluation and should not be interpreted as a prediction of the remaining life expectancy of the air conditioner. Special HVAC license is required to check refrigerant pressures and other internal components. If you wish to have a technical evaluation, we suggest you have the system serviced and evaluated by a licensed HVAC technician. the home inspector is not required to: operate cooling systems when weather conditions or other circumstances may cause equipment damage; inspect window air conditioners; or inspect the uniformity or adequacy of cool-air supply to the various rooms.

S = Item is satisfactory	R = Item needs repair	I = Item needs investigated	NP = Item not present N	I = Item not inspected
HVAC Distribution	Report Number T2U144R66190		= Tips, Tools, and Savin	ngs S R I NP NI
DUCTS- (includes supports & in	nsl.)	None Uninsulated Sheet Metal		V
FILTER - Size(s): 20 X 20 X	X 1			~
	AD	DITIONAL DUCT ITEM (IF NEI	EDED)	
				✓

S = Item is satisfactory		I = Item needs investigated	\mathbf{NP} = Item not present	NI = Item not inspected
INTERIOR	Report Number T2U144R66190		= Tips, Tools, and	Savings S R I NP NI
WALLS & CEILINGS	S			
	front coat closet ceiling. No evidence ling with proper preparation.	of active leaks observed over this ar	ea. Ceiling is dry at time of the	inspection.
FLOORS (does not inc	clude carpeting or finish treatments)		
Slope noted to the first the framing. Flooring feels	d need stretching along the second flo floor hallway beside the hall bathroom secure. e wood flooring in the front office. Re	n. Finished ceiling in the basement un	nder this area prevents viewing	the floor
STEPS & STAIRWAY	//S			□ ✓
				N. H. W.
INTERIOR BALCON	Y & RAILINGS			□ ✓
COUNTERS & BUILT	Γ-IN CABINETS (representative #)			
INTERIOR DOORS (representative #)			
	room door sticks when closing. Reconset doors drag against the bathroom f			door or
WINDOWS (interior s	side of windows)			
Windows are stuck and	hard to open through the home. Recor	mmend freeing at least one window in	n every room to allow emergen	cy egress.
	ADDIT	IONAL INTERIOR ITEMS (IF N	EEDED)	
				✓

S = Item is satisfactory $R = Ite$	em needs repair		needs investigated	$\mathbf{NP} = \mathbf{Iter}$	m not present	NI = Item not inspected
INSULATION & VENTILA		t Number 44R66190			= Tips, Tools, and Sa	avings S R I NP NI
BASEMENT INSULATION- 6 1/4 in. thick	Blown	Cellulose	Fiberglass	None	Roll/batt	<u> </u>
Basement has 6 1/4 +/- " of fiberglass b	lanket insulation w	hich meets curren	t energy standards.			
CRAWLSPACE INSULATION- in. thick	Blown	Cellulose	Fiberglass	None	Roll/batt	
ATTIC INSULATION- 12 1/2 in. thick	Blown	Cellulose	Fiberglass	None	Roll/batt	
12.5 +/- inches of blown fiberglass insu	lation is present in	attic and is rated	at R-30+/- which m	eets current ene	rgy standards.	
VAPOR RETARDERS-	Kraft backe	d paper Othe	er	Plastic		\checkmark
CRAWLSPACE VENTILATION-	8" x 16" Fo	undation Vents	Fan		Other	
ATTIC VENTILATION-	Gable	Louvers	Powerfan R	idge So	ffit Static	V
WHOLE HOUSE FAN						
BATHROOM VENTS- To attic & ov	ver to soffit					
DRYER VENT- To exterior wall						
	ADDI	FIONAL INSUL	ATION ITEMS (I	F NEEDED)		
	11001			i (Liber)		
Note: Items noted "R" (needing rep purchase or sale. The home inspec with household appliances. The ho move floor insulation where plumb	tor is not required me inspector shall:	to report on: cond move insulation	cealed insulation an where readily visib	d vapor retarder de evidence indi	s; or venting equipm cates the possibility	nent that is integral of a problem; and

	Penort Numbe	Item needs investigated	\mathbf{NP} = Item not present	NI = Item not inspected
BUILT-IN KITCHEN APP	T2U144R6619		III = Tips, Tools, and	d Savings SRINPNI
KITCHEN # 1	<u>Manufacturer</u>	Model #	Serial #	
DISHWASHER	Frigidaire	TH41198736	FGHD2465NF1A	
A visible high loop is not present at the dishwasher drain line to prevent water			son install a high loop or an air	gap at the
RANGE- Gas	Frigidaire	FGGF3054MFG	VF40497536	
OVEN- Gas	Frigidaire	FGGF3054MFG	VF40497536	
TRASH COMPACTOR				
GARBAGE DISPOSAL	ISE / Badger	5-81	07071762193	
RANGE HOOD VENT	Frigidaire	FGMV174KFC	9G34800811	
MICROWAVE (Built-in)	Frigidaire	FGMV174KFC	9G34800811	
REFRIGERATOR	Frigidaire	FGHB28668F3	4A40803078	
	ADDITIONAL A	APPLIANCE ITEMS (IF N	NEEDED)	

Note: Washers and dryers are normally considered personal property and are not checked if present. Due to time constraints, self cleaning options on ovens are not tested. Since appliances are only turned on for a short period of time, extensive testing of timers, thermostats and other controls is not possible. Any appliance that is over ten years old is considered past its normal life expectancy. Appliances can fail at any time regardless of age: consider purchasing a home warranty service contract to cover repair or replacement. The home inspector is not required to inspect: locks, timers, self-cleaning oven functions, or thermostats for calibration or automatic operation; non built-in appliances; or refrigeration units. The home inspector is not required to operate: appliances in use; or any appliance that is shut down or otherwise inoperable.

SAFETY INSPECTON	Report Number T2U144R66190				= Tips, Tools, and Savings
SMOKE DETECTORS # - Thro	•	SMOKE DETE	CTORS WORK? -	Yes	- Tips, Tools, and Savings
		S.MORE DETE		105	
CARBON MONOXIDE DETECT	TORS # - None	CARBON MONOXIDE DETECT	TORS WORKING? -		
DEADBOLTS INSTALLED? -	Yes	DEADBO	OLTS WORKING? -	Yes	
FIRE EXTINGUISHERS # - No	one				
SECURITY SYSTEM INSTALL	ED? Yes				
	AI	DDITIONAL SAFETY ITEMS (IF NEED	DED)		

We are proud to provide this Safety Report with support from Nationwide Insurance, ADT, and Safe Homes for Safe Kids.

Please review entire report for other safety related items.







SUPPLEMENTAL INFORMATION

Report Number T2U144R66190

All directional references are made facing the front door of the house. This report is intended for the exclusive use of our client. Items noted "R" (needing repair) or "I" (needing further investigation) should be repaired and/or evaluated by a qualified repair person prior to purchase or sale. This is a visual inspection of readily accessible components only and is not technically exhaustive.

Home inspectors are NOT required to report on: the life expectancy of any component or system; the causes of the need for a repair; the methods, materials and costs of corrections; the suitability of the property for any specialized use; compliance or noncompliance with codes, ordinances, statutes, regulatory requirements or restrictions; the market value of a property or its marketability; the advisability or inadvisability of purchase of the property; any component or system that was not inspected; the presence or absence of pests such as wood damaging organisms, rodents, or insects; cosmetic damage, underground items, or items not permanently installed - any information given on these items should be considered incomplete and should be further evaluated prior to sale.

Home inspectors are NOT required to: offer warranties or guarantees of any kind; calculate the strength, adequacy, or efficiency of any system or component; enter any area or perform any procedure that may damage the property or its components or be dangerous to adversely affect the health or safety of the home inspector or other persons; operate any system that has been shut down or otherwise inoperable; operate any system that does not respond to normal controls; move personal items, panels, furniture, equipment, plant life, soil, snow, ice, or debris that obstructs access or visibility; determine the presence or absence of any suspected adverse environmental condition or hazardous substance - including toxins, carcinogens, noise, contaminants in the building or in soil, water or air; determine the effectiveness of any system installed to control or remove suspected hazardous substances; predict future condition, including failure of components; project operating costs of components; evaluate acoustical characteristics of any system or component; inspect special equipment or accessories that are not listed in this report; disturb insulation except: where readily visible evidence indicates the possibility of a problem, where plumbing drain/waste pipes penetrate floors and adjacent to earth filled stoops or porches and at exterior doors - any information given on these items should be considered incomplete and should be further evaluated prior to sale. Home inspectors shall NOT: Offer or perform any act or service contrary to law; offer to perform engineering, architectural, plumbing, electrical or any job function requiring an occupational license in the jurisdiction where the inspection is taking place, unless the home inspector holds a valid occupational license, in which case the home inspector shall inform the client that the the home inspector is so licensed, and therefore qualified to go beyond this section and perform additional inspections beyond those listed as line items in this report.

STRUCTURAL

Note: Items noted "R" (needing repair) or "I" (needing further investigation) should be repaired and/or evaluated by a qualified repair person prior to purchase or sale. Due to recent advances in modular construction techniques, it is sometimes difficult to determine if a home is modular or "stick built". Therefore, no determination was made by the inspector other than a general framing description.

EXTERIOR

Note: Items noted "R" (needing repair) or "I" (needing further investigation) should be repaired and/or evaluated by a qualified repair person prior to purchase or sale. Conditions behind siding, gutters, awnings and heavy shrubbery are not visible and are expressly excluded from this report. Representative site drainage cannot be accessed if it has been dry for an extended period of time. No guarantee is made for compromised insulation seals on windows and doors because this condition may only be apparent during certain weather conditions. The home inspector is NOT required to inspect storm windows & doors, screening, shutters, awnings, and similar seasonal accessories; fences; presence of safety glazing in doors and windows; garage door remote controls; geological and soil conditions; recreational facilities (including spas, saunas, steam baths, swimming pools, tennis courts, playground equipment, and other exercise, entertainment or athletic facilities); detached buildings or structures; any environmental hazard or buried fuel tanks.

ELECTRICAL

Note: Items noted "R" (needing repair) or "I" (needing further investigation) should be repaired and/or evaluated by a qualified repair person prior to purchase or sale. The home inspector is not required to: insert any tool, probe, or testing device inside the panels; test or operate any over current device except ground fault circuit interrupters; dismantle any electrical device or control other than to remove the covers of the main and auxiliary distribution panels; operate and test smoke detectors when detectors are part of a central system. The home inspector is not required to inspect: low voltage systems; security system devices, heat detectors, or carbon monoxide detectors; telephone, security, cable TV, intercoms, or other ancillary wiring that is not a part of the primary electrical distribution system; or built-in vacuum equipment. "Representative number" means, for multiple identical components such as electrical outlets, one such component per room. Safety Note: To help prevent fatal electric shocks, modern standards require Ground Fault Circuit protection at the receptacles serving the kitchen, bathrooms, & laundry (within 6' of sink); also garage, unfinished basements, exterior, crawl space, whirlpools, spas, pools, & fountains - if not present, client should add ground fault protection for personal safety.

PLUMBING

Note: Items noted "R" (needing repair) or "I" (needing further investigation) should be repaired and/or evaluated by a qualified repair person prior to purchase or sale. If well water is used for drinking purposes, we recommend it be tested by a lab or the health dept. Underground septic systems, sewer lines, and water treatment equipment are not inspected. If present, we recommend a septic system inspection and/or contractor evaluation before closing. The home inspector is not required to: state the effectiveness of anti-siphon devices; determine whether water supply and waste disposal systems are public or private; operate automatic safety controls; operate any valve except water closet flush valves, fixture faucets, and hose faucets. The home inspector is not required to inspect: water conditioning systems; fire and lawn sprinkler systems; on-site water supply quantity and quality; on-site waste disposal systems; foundation irrigation systems; bathroom spas, except as to functional flow and functional drainage; swimming pools; solar water heating equipment: or inspect the system for proper sizing, design, or use of proper materials.

SUPPLEMENTAL INFORMATION

Report Number T2U144R66190

INTERIORS

Note: Items noted "R" (needing repair) or "I" (needing further investigation) should be repaired and/or evaluated by a qualified repair person prior to purchase or sale. "Representative number" means, for multiple identical components such as interior doors and windows, one such component shall be operated per room. The home inspector is not required to inspect: paint, wallpaper, and other finish treatments on: interior walls, ceilings, and floors; carpeting, draperies, blinds, or other window treatments.

ROOF

Note: Items noted "R" (needing repair) or "I" (needing further investigation) should be repaired and/or evaluated by a qualified repair person prior to purchase or sale. Apparent serviceability of roofing system is reported but is not a warranty or guarantee of the remaining life expectancy. The home inspector is NOT required to walk on the roofing or inspect attached accessories including solar systems, antennae and lightning arrestors.

INSULATION

Note: Items noted "R" (needing repair) or "I" (needing further investigation) should be repaired and/or evaluated by a qualified repair person prior to purchase or sale. The home inspector is not required to report on: concealed insulation and vapor retarders; or venting equipment that is integral with household appliances. The home inspector shall: move insulation where readily visible evidence indicates the possibility of a problem; and move floor insulation where plumbing drain/waste pipes penetrate floors, adjacent to earth-filled stoops or porches, and at exterior doors.